UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO. : 6,886,886 B2 DATED

: May 3, 2005

INVENTOR(S): Dinesh C. Seksaria et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 3,

Line 64, insert --, -- after "members".

Column 6,

Line 23, "owing" should read -- the following --. Line 24, insert -- parts are -- after "like".

Column 9,

Line 53, insert -- side 118 -- after "first".

Column 11,

Line 45, insert -- the -- after "by".

Line 52, delete "(not yet assigned)", insert -- (10/271,449) --.

Column 12,

Line 58, "304,306" should read -- 304, 306 --.

Column 15,

Line 59, "gassembly" should read -- assembly --.

Lines 61 and 64, "200-100" should, in both instances, read -- 200-400 --.

Signed and Sealed this

Twelfth Day of July, 2005

JON W. DUDAS Director of the United States Patent and Trademark Office